

	Type	Hits	Search Text
1	BRS	1056	361/42.ccls.
2	BRS	17	361/42.ccls. and (housing same interrupt\$3 same detection)
3	BRS	2606	ground same fault same interrupt\$3
4	BRS	51	(ground same fault same interrupt\$3) and (housing same interrupt\$3 same detection)
5	BRS	45	("6052265" "5982593" "5966280" "5956218" "5875087" "5825599" "5754114" "5726900" "5715125" "5642052" "5515218" "5481194" "5477412" "5459630" "5363269" "4829289" "4816957" "4292" "585" "4280092" "3932790").pn.
6	BRS	15	("5266039" "5933063" "5510760" "5943199" "4002951" "4595894" "5594398").pn.
7	BRS	3	6515564.pn.
8	BRS	1	"6525541" .pn.
9	BRS	578	bistable near relay
10	BRS	511	bistable adj relay
11	BRS	4	((bistable adj relay) (bistable adj latching adj relay)) same ground same fault
12	BRS	2	"6349908" .pn.
13	BRS	2	"6349908" .pn.
14	BRS	3	"6515564" .pn.

	DBs	Time Stamp	Comments	Error Definition
1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:36		
2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:49		
3	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 10:48		
4	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 11:51		
5	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:09		
6	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:10		
7	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:24		
8	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:32		
9	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:33		
10	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:34		
11	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:42		
12	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 13:42		
13	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 15:54		
14	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/05/28 15:54		